



Report N00014-80-C-0437-1

# STUDY OF MECHANO-CHEMICAL MACHINING OF CERAMICS AND THE EFFECT ON THIN FILM BEHAVIOR

H. Vora and R.J. Stokes Honeywell Inc. Corporate Technology Center 10701 Lyndale Avenue South Bloomington, MN 55420

June 1981

222

-

¥

Annual Technical Report for Period 1 May 1980 — 30 April 1981

Reproduction in whole or in part is permitted for any purpose by the United States Government.

Prepared for

Office of Naval Research 800 North Quincy Street Arlington, VA 22217 SELECTE MAR 2 6 1982

Under Contract No. N00014-80-C-0437 Contract Authority Identification No. NR 032-601

DISTRIBUTION STATEMENT A

Approved for public release; Distribution Unlimited

८८ ०७ ४३ ०१३

UNCLASSIFIED


REPORT DOCUMEN		
	ITATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOV'T ACCESSION NUMBER	3. RECIPIENT'S CATALOG NUMBER
N00014-80-C-0437-1	AD-A112574	
4. TITLE (AND SUBTITLE) Study of Mechano-Chemical Ma Effect On Thin Film Behavior.	chining of Ceramics and the	5. TYPE OF REPORT/PERIOD COVERED Annual Technical Report 1 May 1980 - 30 April 1981 6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(S)		8. CONTRACT OR GRANT NUMBER(S)
H. Vora and R. J. Stokes	•	N00014-80-C-0437
9. PERFORMING ORGANIZATIONS NAME/A Honeywell Corporate Technolog 10701 L yndale Avenue South Bloomington, MN 55420		10. PROGRAM ELEMENT PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME/ADDRES	is .	12. REPORT DATE June 1981
Office of Naval Research 800 North Quincy Street Arlington, VA 22217		13. NUMBER OF PAGES
	S (IF DIFFERENT FROM CONT. OFF.)	31
•		UNCLASSIFIED
		15a. DECLASSIFICATION DOWNGRADING SCHEDULE
16. DIŜTRIBUTION STATEMENT (OF THIS F	DISTRIBU	od for public release; ribution Unlimited
17. DISTRIBUTION STATEMENT (OF THE A		
19. KEY WORDS (CONTINUE ON REVERSE Mechano-chemical Polishing, Se;		•
20. ABETRACT (CONTINUE ON REVERSES	IDE IF NECESSARY AND IDENTIFY BY	), Si, and both single-crystal and tape-cast
Al <sub>2</sub> 0 <sub>3</sub> using the technique of me an abrasive whose hardness is less that are also flat. An evidence for not obtained in the case of MgO. The mechano-chemical polishing	schano-chemical polishing. In the strain that of the workpiece to port mechano-chemical polishing in which was polished using tale, regelects, however, were readily of the strain that was polished using tale.	nis technique, the emphasis is on employing produce damage-end scratch-free surfaces in the form of scratch-free surfaces was tock salt, calcite, and fluorite as abrasives. Tobserved when Si was polished using CaCO3, a plate of window glass using no abrasive.

CONCLASSIFICATION OF THIS PAGE (WHO). Abstract - Mechano-chemical interferometry, optical microscop	ly-polished surfaces wen	e characterized us	ing RHEED, profilometry
nterferometry, optical microscop	y, and electron spectros	copy for chamica	A COLOR OF THE COL
			>
	•		<i></i>
•			
	·		
•			

ii

#### **Preface**

This report covers work performed under Office of Naval Research Contract No. N00014-80-C-0437 during the period 1 May 1980 to 30 April 1981. The authors would like to thank Dr. K.D. McHenry for his association with this project in its early stages, Ms. J.M. Hanson for experimental measurements, and Mr. D.J. Sauve, Jr. for excellent technical support throughout this work. ESCA data of mechano-chemically-polished samples were obtained by Dr. T.W. Orent and Mr. A.D. Beck, and RHEED and X-ray work was performed by Mr. C. Knudson.





### **Table of Contents**

Section		Page
1	INTRODUCTION	1
2	EXPERIMENTAL	3
3	RESULTS	5
	Magnesia Silicon Alumina	5 6 17
4	DISCUSSION	24
	DISTRIBUTION LIST (Basic)	27
	DISTRIBUTION LIST (Supplementary)	29

### List of Illustrations

Figure		Page
1	Photographs of polishing machines	4
2	Photomicrographs of the etched surfaces of MgO polished dry on nylon using NaCl	7
3	Photomicrographs of the etched surfaces of MgO polished wet on glass using NaCl	8
4	Surface profile and Nomarski micrograph of a Si wafer taken before mechano-chemical polishing	10
5	Surface profile and Nomarski micrograph of a Si wafer taken after mechano-chemical polishing	11
6	RHEED pattern of a mechano-chemically-polished silicon	12
7	ESCA spectra of a silicon crystal polished with CaCO <sub>3</sub>	13
8	ESCA spectra of a silicon crystal polished with BaCO <sub>3</sub>	14
9	ESCA spectrum of fracture surface of silicon	15
10	Surface figures of mechano-chemically-polished silicon crystals	16
11	Scratches on the surface of a mechano-chemically-polished silicon made visible by Wright etch	17
12	RHEED patterns of sapphire	20
13	Nomarski micrographs of mechano-chemically-polished sapphire and tape-cast alumina	21
14	Surface profiles of mechano-chemically-polished sapphire and tape-cast alumina	22
15	Surface figures of mechano-chemically-polished sapphire	23

### List of Tables

Table		Page
1	REMOVAL RATES (mg/hr) FOR MAGNESIUM OXIDE SINGLE CRYSTALS	6
2	POLISHING RATES FOR ALUMINA	18

### Section 1 Introduction

In a variety of applications, particularly those associated with optics and electronics, materials possessing smooth, damage-free, and flat surfaces are required. Such surfaces are difficult to obtain using conventional techniques in which abrasives with hardnesses greater than that of the workpiece are employed. Hard abrasives introduce scratches and a damaged layer, which must be removed by a final treatment. This treatment often consists of chemical polishing in which the material is removed by chemical rather than mechanical means. However, chemical polishing rapidly degrades the flatness of the workpiece and often introduces orange-peel structure on the surface. In order to overcome these problems, the technique of mechano-chemical polishing was recently introduced by Yasunaga et al., who have reported that this technique can yield damage- and scratch-free flat surfaces at surprisingly high rates of material removal.

In mechano-chemical polishing, the emphasis is on employing an abrasive whose hardness is less than that of the workpiece. Since such an abrasive cannot damage or scratch the workpiece, the technique yields damage- and scratch-free surfaces. Although the abrasive employed in mechano-chemical polishing is soft, it yields high removal rates because of the chemical reaction that occurs at the contact points of the abrasive and the workpiece. The transformed regions are believed to be extremely small (of the order of 100Å), and the resulting phase (since its properties differ from those of the workpiece and abrasive) is removed by subsequent contact with other abrasive grains.

Mechano-chemical polishing is performed in a manner similar to conventional polishing using conventional polishing machines. However, in order to promote a chemical reaction, it is often necessary to generate high temperatures at the contact points of the abrasive and the workpiece. A simple way to accomplish this is by applying high pressure on the workpiece and performing the mechano-chemical polishing dry. In some cases, chemical reactions can be induced at moderate temperatures, and significant removal rates are observed when the mechano-chemical polishing is performed wet. The term wet refers to employment of a polishing medium consisting of a slurry of soft abrasive in water, as opposed to use of loose powder in dry polishing. In any case, one expects the applications of mechano-chemical polishing technique to be restriced to hard materials, that is, those materials which can withstand pressure required to react chemically with the abrasive without deformation or fracture.

The work performed during this contract had two long-term objectives: 1) to understand the mechanisms involved in mechano-chemical finishing by better characterization of

N. Yasunaga, N. Tarumi, A. Obera, and O. Imanaka in The Science of Ceramic Machining and Surface Finishing II, B.J. Hockey and R.W. Rice, editors, National Bureau of Standards Special Publication 562, 1979, p. 171.

the topography and chemical strucure of both the finished surfaces and the residual polishing powders, and 2) to determine the consequences of mechano-chemically-finished surfaces on the physical performance of materials.

Physical properties of interest in this program were mechanical strength, and electrical conductivity and adhesion of metal films. Mechanical strength is a direct physical property in that it is directly affected by the surface conditions, whereas electrical conductivity, or adhesion of metal films, is an indirect physical property, which is influenced by the surface finish of the substrates.

Efforts have been made to mechano-chemically polish three different materials, which, in the increasing order of hardness are single-crystal magnesia, single-crystal silicon, and single-crystal and tape-cast alumina. No evidence for mechano-chemical polishing was obtained in the case of magnesia. However, the contractor was able to confirm the occurrence of mechano-chemical polishing effect in the case of silicon, as well as alumina. This report describes the results of the contractor's efforts to mechano-chemically polish these materials, as well as to characterize the mechano-chemically-polished surfaces, using several analytical techniques.

### Section 2 Experimental


Attempts to mechano-chemically polish various materials were made on two polishing machines: a Precision Polishing Machine Model PM2, manufactured by Hacker Instruments, Inc. of Fairfield, New Jersey, and a Strasbaugh Polishing Machine, Model 6Y-1, manufactured by R. Howard Strasbaugh, Inc. of Huntington Beach, California. The machines are shown in Figure 1. In the tests conducted on the Precision Polishing Machine, the pressure acting on the sample was readily determined by measuring the weight of the sample holder, adding to it any extra weights placed on the sample holder, and dividing the total with the surface area being polished.

The Strasbaugh Polishing Machine used in the tests was equipped with an air pressure system, the control unit of which contained a gauge which showed pressure in psi. This pressure could be adjusted over a range from 0 to 100 psi. In a typical experimental situation, 1 psi translated into a load on the sample of approximately 1 lb (0.45 kg).

Mechano-chemical polishing experiments were conducted both in wet and dry conditions. In the dry condition, the lap was simply covered with the desired abrasive at the start of the run and replenished as required. In the wet condition, a slurry containing 2-10 weight percent of soft abrasive was sprayed on the lap frequently to ensure that the wet condition remained throughout the experiments.

Attempts to measure removal rates were made for MgO,  $Al_2O_3$ , and Si. MgO single crystals used for polishing studies were of dimensions  $0.75 \,\mathrm{cm} \times 0.75 \,\mathrm{cm} \times 0.5$ -lmm. All six faces of these crystals were cleaved along  $\{100\}$  planes. The procedure used for computation of the removal rates of MgO was to accurately measure the cross-sectional area of the sample and its thickness before and after polishing for a given period of time. From these data and the known density of MgO  $(4.0 \,\mathrm{gm/cc})$ , the removal rates in mg/hr were computed. Removal rates in the case of  $Al_2O_3$  were determined by measuring the decrease in size of Knoop indentations made using a load of 300 grams. It was necessary to make a series of indentations on a given specimen because only 2 or 3 out of 10 indentations retained their shapes during polishing; several cracks appeared near the remaining indents and accurate measurements of their size as a function of polishing time could not be made. The Knoop indentation technique was tried, with little success, to determine the wear rates of silicon single crystals.

Some caution should be exercised in connection with the removal rate data. There are many factors that contribute to the removal rates obtained in mechano-chemical polishing, some of which are known and can be controlled readily (e.g., load on the sample and the polishing wheel speed). There are others which influence removal rates in a manner that is not clearly understood at present and attempts to control them have not been made yet. Some examples of these factors are the initial flatness and surface roughness of the sample, how the lap is charged with the abrasive, whether the lap has been used previously or not, and in the case of wet mechano-chemical polishing of silicon single crystals, the concentration and pH of the slurry.



(a) Precision Polishing Machine, Model PM2 (Hacker Instruments)



(b) Strasbaugh Polishing Machine, Model 6Y-1

Figure 1 \*\*hotographs of polishing machines

### Section 3 Results

#### **MAGNESIA**

Single crystals of magnesia were selected for the present study because they could be cleaved easily along {100} planes. In addition, the dislocations in MgO can be revealed easily by the etching techniques, a fact that has contributed significantly to the understanding of the deformation and fracture behavior of this material.

Attempts to mechano-chemically polish MgO single crystals were made on the Precision Polishing Machine using talc (3 MgO·4SiO $_2$ · $H_2$ O), rock salt (NaCl) calcite (CaCO $_3$ ) and fluorite (CaF $_2$ ) as soft abrasives. The respective hardnesses of these abrasives on the Mohs scale are 1, 2, 3, and 4, as compared to  $\sim 5$  for magnesia. Some magnesia crystals were polished using these abrasives on a smooth glass lap. Since most glasses are harder than magnesia, they can scratch magnesia, and thus, contribute to the observed removal rates. For this reason, several MgO crystals were polished on a brass wheel covered with an adhesive-backed Nylon cloth\*. The laps of both types were  $\sim 25$ cm in diameter.

In mechano-chemical polishing, the load applied to the sample during polishing and the polishing speed are two important parameters. In the case of MgO crystals of 0.75cm × 0.75cm in cross section, the applied load was either 1.36kgs or 4.4kgs. At higher loads, MgO crystals fractured frequently and the polishing experiments could not be conducted successfully. The rotation speed of polishing laps was either 30 r/min or 60 r/min during polishing of MgO.

Following polishing, samples were examined in an optical microscope to see if their surfaces were scratch-free. The samples were then etched in a solution of 5 parts saturated ammonium chloride (NH<sub>4</sub>Cl), 1 part concentrated sulfuric acid (H<sub>2</sub>SO<sub>4</sub>), and 1 part distilled water, and examined again. Some polished MgO crystals were cleaved on a plane perpendicular to the polished surface and etched in the above solution to determine the extent of sub-surface damage.

Effects of various polishing parameters on the removal rates of MgO are summarized in Table 1. It is seen that a material removal took place in every polishing situation attempted. It was suggested earlier that glass, since it is harder than MgO, could contribute to the observed removal rates when used as a lap material. The observed removal rates, however, were not consistently higher when MgO was polished on a glass lap, as compared to Nylon-covered brass lap. For example, the removal rates observed in attempts to wet mechano-chemically polish MgO using talc or CaCO<sub>3</sub> were higher when polished on a Nylon covered brass lap.

\* Buehler Ltd., Evanston, Illinois

TABLE 1. REMOVAL RATES (mg/hr) FOR MAGNESIUM OXIDE SINGLE CRYSTALS

					<del></del>		Polishing E	nvironment							
					٧	Vet			Dr	у					
				Wheel Speed				Wheel Speed							
				Low (30 r/min) High (60 r/min)			0 r/min)	Low (30 r/min) High (60 r/m			80 r/min)				
Surface	Glass	ass	ass	Load	Load	Load	High	Talc NaCl CaC03	1.135 5.499 3.719	Talc NaCl	7.008 6.66	Talc NaCl CaCO <sub>3</sub>	66.314 0.797 139.89	Talc NaCl	163.09 5.634
		Lc	Lc				Lc	Lc	Lc	Lc	אן	Low	Talc NaCl	5.30 2.287	Talc NaCl
Wheel	Nylon	Load	High	Talc CaCO <sub>3</sub>	11.91 4.06	Talc CaCO <sub>3</sub>	14.153 7.02	Talc NaCl CaCO <sub>3</sub> CaF <sub>2</sub>	1.18 84.18 2.4 8.45	Talc	3.175				
		ו	Low	Talc NaCl	26.94 5.71	Talc	16.73	Talc NaCl	9.45 36.04	Talc	5.46				


All powders screened to 325 mesh (45µm).

Metallographic examinations of the surfaces of polished MgO crystals gave no evidence of mechano-chemical polishing effect. The polished surfaces were scrached and damaged. Etching studies revealed a correlation between the removal rates and the extent of surface and sub-surface damage. High removal rates were associated with high dislocation density on the surface and, thus, greater extent of sub-surface damage (see Figure 2). Low removal rates were associated with smoother surfaces and a shallow sub-surface damage (see Figure 3).

X-ray analysis of debris obtained by polishing MgO dry on glass using tale, and that obtained by polishing it wet on glass with NaCl gave diffraction patterns of only tale and NaCl. This data and the results of metallographic examinations indicate that true mechano-chemical effect did not occur in the case of MgO for the conditions chosen in this work. The material is apparently removed by plastic flow and mechanical impact fracture. Thus, magnesia is too plastic (or weak) to support high pressures and temperatures necessary at contact points in mechano-chemical polishing.

#### SILICON

Most of the silicon single-crystal samples used in this work were 7.5cm in diameter, 0.05cm thick, and were of [100] orientation. Efforts to mechano-chemically polish these



(a) Polished surface




(b) Cross section showing the depth of sub-surface damage

Figure 2. Photomicrographs of the etched surfaces of MgO polished dry on nylon using NaCl



(a) Polished surface



(b) Cross section showing the shallow depth of sub-surface damage

Figure 3. Photomicrographs of the etched surfaces of MgO polished wet on glass using NaCl

samples were made using three abrasives, CaCO<sub>3</sub>, BaCO<sub>3</sub>, and MgO, and using 25-cm diameter laps of either linen Bakellite or PVC. In a typical polishing attempt, a rotation speed of 50 r/min was employed for the lap and a pressure of about 100 gm/cm<sup>2</sup> was applied on the specimen. Under these experimental conditions, the laps of PVC wore out faster than the laps of linen Bakellite, and most of the polishing was performed on the laps of linen Bakellite.

Scratch-free and highly reflecting surfaces were readily obtained when silicon samples were wet or dry mechano-chemically polished using any of the above three abrasives. Slurries used for wet mechano-chemical polishing contained about 10 weight percent of the soft abrasives.


Attempts to measure the removal rates realized during mechano-chemical polishing of silicon using the Knoop indentation technique met with little success. Samples used for these measurements were 3mm in thickness and  $\sim 1 \text{cm} \times 1 \text{cm}$  in cross section, and the Knoop indentations were made using the loads in the range 50-500g. Even at low loads, several cracks formed near the diagonals of the indents, resulting in a rapid distortion of their shapes during mechano-chemical polishing.

An indication of the rate at which silicon is removed during mechano-chemical polishing can be obtained from surface roughness data shown in Figures 4 and 5. Figure 4 shows the surface profile, as well as the Nomarski micrograph, of a 7.5-cm diameter silicon wafer before polishing. Figure 5 shows the surface profile and the Nomarski micrograph of the same silicon wafer after 2 hours of dry mechano-chemical polishing with  $CaCO_3$ . It can be seen that mechano-chemical polishing for 2 hours reduces the peak-to-peak roughness of silicon from a value of  $\sim 4\mu$ m to a value of  $\sim 40$ Å. This corresponds to a removal rate of at least  $2\mu$ m/hr.

Figure 6 shows the reflection high-energy electron diffraction (RHEED) pattern of a sample of silicon which was wet mechano-chemically polished with  $CaCO_3$ . This pattern was obtained using a 100-kV electron beam which has a depth of penetration of  $\sim 50 \text{\AA}.^2$  The presence of spots and the Kikuchi lines seen in the RHEED pattern indicates that the mechano-chemically-polished silicon surface is of high perfection.

Several samples of mechano-chemically-polished silicon were examined using the technique of electron spectroscopy for chemical analysis (ESCA). The objectives were to see if the polished surfaces were contaminated by the polishing abrasive or a reaction product of the polishing compound and the silicon, and to determine the extent of oxidation of silicon. The sensitivity of ESCA technique is about 0.001 monolayer, although it varies with material and experimental conditions. Of particular interest in the case of silicon is the  $Si_{2P}$  peak (binding energy, Eb = 99eV) and the peak at Eb = 103eV which is caused by oxidation of silicon. The smaller the height of this peak relative to the  $Si_{2P}$  peak, the smaller the extent of oxidation of silicon. Values reported for this ratio are 0.3 for conventionally-polished silicon samples and in the range of 0.12 - 0.18 for silicon samples polished mechano-chemically with  $BaCO_3$ .

<sup>2.</sup> J.L. Whitton, J. Appl. Phys. 36, 3917 (1965).







Figure 4. Surface profile and Nomarski micrograph of a Si wafer taken before mechano-chemical polishing






Figure 5. Surface profile and Nomarski micrograph of a Si wafer taken after mechano-chemical polishing




Figure 6. RHEED pattern of a mechano-chemically-polished silicon

ESCA spectra of a silicon sample wet mechano-chemically polished with  $CaCO_3$  are shown in Figure 7. Spectrum (a) was obtained by scanning the polished surface, and spectrum (b) was obtained by scanning the sample again after sputter etching the polished surface to a depth of  $\sim 50 \text{Å}$ . Features near  $Si_{2P}$  peaks are shown on an expanded scale in (c). The corresponding spectra of a silicon sample wet mechanochemically polished with  $BaCO_3$  are shown in Figure 8. For comparison purposes, the spectrum obtained by scanning the fracture surface of silicon is shown in Figure 9. Note that there is no Ba or Ca contamination of the polished silicon surfaces, and that the peak at 103-eV almost disappears after sputter etching to a depth of  $\sim 50 \text{Å}$ . The ratios of the height of this peak to the height of  $Si_{2P}$  peak in the spectra of silicon surfaces polished with  $BaCO_3$  and  $CaCO_3$  is  $\sim 0.16$ , which is in agreement with the values reported by Yasunaga et al.<sup>1</sup>


Measurements using an interferometric technique of the surface figures of mechanochemically-polished silicon crystals of various cross sections indicate that the surface figure degrades with the increasing cross section of the sample. For samples of about 1cm  $\times$  1cm in cross section, flatness in the range of 1/5th of a wave to 1 wave (at 633nm) has been measured. For samples of 2.5cm in diameter, flatness in the range of 1 $\lambda$  to 3 $\lambda$  has been measured. Using a hybrid approach in which the samples are polished to the desired flatness conventionally and then mechano-chemically to remove the damaged layer and scratches introduced by conventional polishing, we have been able to achieve a flatness of 1/10 of a wave at 633nm. Figure 10 shows the surface figures of some mechano-chemically-polished silicon samples.

Several samples of mechano-chemically-polished silicon crystals were etched in a freshly prepared Wright etchant.<sup>3</sup> All these samples appeared scratch-free before etching. On the surfaces of some of these samples, a few isolated scratches appeared after etching for a period of about 1 minute (see Figure 11). It is believed that the chunks of silicon that often chip off from the periphery of the sample during mechano-chemical polishing are contaminating the lap and causing these scratches.


<sup>3.</sup> M.W. Jenkins, J. Electrochem. Soc., 124, 757, (1977).



(a) Polished surface




(b) After sputter etching 50Å from the polished surface




(c) Features near Si<sub>2p</sub> peak in spectra (a) and (b) shown on an extended scale


Figure 7. ESCA spectra of a silicon crystal polished with CaCO<sub>3</sub>



(a) Polished surface



(b) After sputter etching 50Å from the polished surface



(c) Features near Si<sub>20</sub> peak in spectra (a) and (b) shown on an extended scale

Figure 8. ESCA spectra of a silicon crystal polished with BaCO<sub>3</sub>






Figure 9. ESCA spectrum of fracture surface of silicon



(a) 3.2cm in diameter



(b) 2.54cm in diameter. Sample (b) was polished flat conventionally before mechano-chemical polishing.

Figure 10. Surface figures of mechano-chemically-polished silicon crystals




Figure 11. Scratches on the surface of a mechano-chemically-polished silicon made visible by Wright etch

#### **ALUMINA**

All efforts to mechano-chemically polish alumina were made on the Strasbaugh Polishing Machine. Single-crystal alumina (sapphire) of (1012) orientation and tapecast alumina were starting materials. Tape-cast alumina was purchased from Coors and the sapphire from Kyocera.

Initial efforts to mechano-chemically polish  $Al_2O_3$  were made on a lap of window glass using talc, NaCl, KCl,  $Fe_2O_3$ , and  $SiO_2$  as abrasives. No significant mechano-chemical polishing of  $Al_2O_3$  was observed when the glass lap was covered with talc, NaCl, or KCl. However, evidence for mechano-chemical polishing was readily obtained when  $Fe_2O_3$  or  $SiO_2$  was used as an abrasive. During this study, it was also observed that the presence of neither  $Fe_2O_3$  nor  $SiO_2$  was necessary to polish  $Al_2O_3$ . The contractor was able to obtain scratch-free samples of  $Al_2O_3$  by simply polishing them on a plate of window glass without any abrasive. Most of the efforts were then concentrated on studying polishing of  $Al_2O_3$  by window glass. Similar polishing effects were later observed when  $Al_2O_3$  was polished on a lap of Pyrex glass.

To get an indication of the rate at which  $Al_2O_3$  was being removed when polished on window glass, three tape-cast alumina samples of 1.25cm  $\times$  1.25cm in cross section were polished flat on a tin lap using 6- $\mu$ m diamond paste. Several Knoop indentations were

then made on one of the samples using a load of 300g and all three samples were polished on window glass using a polishing load of 4.5kg and a lap rotation of 60 r/min. The decrease in lengths of long diagonals of Knoop indents were measured as a function of polishing time for a period of  $\sim 2$  hours, the time it took to obtain scratch-free surfaces on all three samples. From these measurements, the average removal rate of alumina over this period was computed. Using this same procedure, the average removal rates of tape-cast alumina and sapphire when polished conventionally using 6- $\mu$ m diamond paste were calculated. The results are summarized in Table 2. It can be seen that removal rates obtained in mechano-chemical polishing are comparable to those obtained in conventional polishing using 6- $\mu$  diamond.

Following the removal rate measurements, attempts were made to polish sapphire samples of 2.5cm  $\times$  2.5cm in cross section and tape-cast alumina samples of 5cm  $\times$  5cm in cross section. A considerable length of time was required to mechano-chemically polish these samples (e.g.,  $\sim$ 2 days to simultaneously polish three sapphire samples and  $\sim$ 5 days to simultaneously polish three tape-cast alumina samples). To prevent the sample holder from getting too hot during these experiments, water was periodically sprayed on the lap. The polishing load used was of  $\sim$ 15kg during polishing of sapphire samples and  $\sim$ 25kg during polishing of tape-cast Al<sub>2</sub>O<sub>3</sub>. At higher loads, the glue used to mount the samples to the sample holder failed and excessive chipping occurred at the edges of the samples. Optical microscopic examinations during these experiments indicated that the removal rates were high in the beginning but decreased rapidly as greater and greater fractions of sample cross sections became smooth. These observations are similar to those made by Ikeda, et al.,4 while mechano-chemically polishing sapphire on silicon laps.

TABLE 2. POLISHING RATES FOR ALUMINA


Sample	Polishing Method	Polishing Rate		
Sapphire (1012 face)	Conventional, 6-µm Diamond	3.3 <b>Å/sec</b>		
Tape-cast Alumina	Conventional, 6-µm Diamond	4.5Å/sec		
Tape-cast Alumina	Mechano-chemical, Window Glass	3.2Å/sec		

M. Ikeda, A. Yamada, Y. Kokaji and S. Kimura in The Science of Ceramic Machining and Surface Finishing II, B.J. Hockey and R.W. Rice, editors, National Bureau of Standards Special Publication 562, 1979, p. 562.


Figure 12 shows the RHEED patterns taken from a sample of Kyocera sapphire before and after mechano-chemically polishing on a window glass lap. Complete absence of any lines or spots in the diffraction pattern taken before mechano-chemical polishing revealed the presence of a thick damaged layer on the surface. Much of this damaged layer was removed by mechano-chemical polishing, as indicated by the presence of spots and Kikuchi lines in the diffraction pattern taken after mechano-chemical polishing.

Optical microscopic examinations of mechano-chemically-polished alumina samples revealed few scratches. Nomarski micrographs and surface profiles of polished surfaces are shown in Figures 13 and 14, respectively. It is seen that mechano-chemical polishing produces a much smoother surface on sapphire (peak-to-peak roughness of  $\sim 40 \text{\AA}$ ) than on tape-cast alumina (peak-to-peak roughness of  $\sim 2500 \text{\AA}$ ). The smoothness in the case of tape-cast alumina is perturbed by the presence of grain boundaries, second phases, and porosity.

Surface figures of several mechano-chemically-polished samples of alumina were measured using a Tropel Interferometer. As in the case of silicon polished on a linen Bakellite lap, the surface figures of mechano-chemically-polished alumina degraded with the increase in the polished surface area from a value of  $\sim 1/5$ th of a wave (at 633nm) for samples of 1.25cm  $\times$  1.25cm in cross section to a value of  $\sim 3$  waves for samples of 5cm  $\times$  5cm in cross section. Surface figures of mechano-chemically-polished sapphire crystals are shown in Figure 15.




(a) Before mechanochemical polishing




(b) After mechanochemical polishing

Figure 12. RHEED patterns of sapphire




(a) Sapphire



(b) Tape-cast alumina

Figure 13. Nomarski micrographs of mechano-chemically-polished sapphire and tape-cast alumina



(a) Sapphire






Figure 14. Surface profiles of mechano-chemically-polished sapphire and tape-cast alumina



(a) Sample cross section 1.25cm × 1.25cm



(b) Sample cross section 2.5cm × 2.5cm

Figure 15. Surface figures of mechano-chemically-polished sapphire

### Section 4 Discussion

Thus far, work performed in this program confirms the occurrence of mechano-chemical polishing effects in the case of Si and  $Al_2O_3$ . In addition to  $CaCO_3$  and  $BaCO_3$  abrasives reported by Yasunaga et al., 1 MgO was identified in this work as another suitable soft abrasive for mechano-chemical polishing of silicon.

Much of the published work on mechano-chemical polishing refers to single-crystal samples of small cross section, typically  $1 \text{cm} \times 1 \text{cm}$ . Attempts were made in this program to apply this technique to single-crystal and polycrystalline samples of much larger cross section (silicon single crystals of up to  $46 \text{cm}^2$  in cross section and alumina samples of up to  $25 \text{cm}^2$  in cross section). It was observed that silicon samples of this size can be polished mechano-chemically in a period of hours, while considerably longer times (4-5 days) were required to polish  $Al_2O_3$  samples. This difference in the behavior of silicon and alumina is not clearly understood and needs additional study.

Evidence for mechano-chemical polishing in the form of scratch-free surfaces has not been obtained in the case of magnesia and it is concluded that magnesia is too soft to withstand pressures required for it to interact chemically with soft abrasives.

In order to extend the application of mechano-chemical polishing techniques to other materials, efforts will be made in this program to mechano-chemically polish GaAs and  $Si_3N_4$ . The hardness of GaAs lies between that of silicon and magnesia and it is also a material of great importance in the electronics industry.  $Si_3N_4$  can be made by tape casting and by hot pressing with thermal conductivity comparable to that of alumina, and with a coefficient of thermal expansion that matches that of silicon. Because of these properties,  $Si_3N_4$  is considered a potential substrate material for very high speed integrated circuit (VHSIC) packaging. This application requires flat, scratch-free surfaces containing minimum pullouts. Since mechano-chemically-polished surfaces of  $Si_3N_4$  are likely to meet these requirements, there is a need to identify suitable soft abrasives for  $Si_3N_4$ .

One of the general objectives of this program is to understand the mechanisms involved in mechano-chemical polishing of ceramic materials. To meet this objective, efforts will be concentrated on further characterizing the mechano-chemically-polished surfaces, and on determining the structure and chemistry of reaction products.

Another general objective of this program is to determine the effects of surface finishing on the physical performance of materials. Research on another program at our facility concerned specifically with the techniques for placing high resolution conductor metallization on ceramic substrates has compared the different surface finishing methods. Thus far, the adhesion of chromium-copper thin film metallization has shown

no sensitivity to the smoothness of the surface finish. The suggestion is that the chromium bonds chemically to the surface to provide the excellent adhesion. It is possible that the less reactive copper might show lower adhesion strengths with smoother surfaces. Further work needs to be performed to understand the mechanisms involved.

## Distribution List (Basic) (Technical and Summary Reports, November 1979)

Organization	Copies	Organization	Copies
_		Naval Construction Batallion	
Defense Documentation Center		Civil Engineering Laboratory	
Cameron Station	12	Port, Hueneme, CA 93043	_
Alexandria, VA 22314	14	ATTN: Materials Division	1
Office of Naval Research		N I Til I aboratory	
Department of the Navy		Naval Electronics Laboratory	
800 N. Quincy Street		San Diego, CA 92152	
Arlington, VA 22217		ATTN: Electron Materials Sciences Division	1
ATTN: Code 471	1	Sciences Division	•
Code 470	1		
0040 110		Naval Missile Center	
Commanding Officer		Materials Consultant	
Office of Naval Research		Code 3312-1	1
Branch Office		Point Mugu, CA 92041	ı
Branch Office			
Building 114, Section D		Commanding Officer	
666 Summer Street	1	Naval Surface Weapons Center	
Boston, MA 02210	•	White Oak Laboratory	
m 11 . 06°		Silver Spring, MD 20910	_
Commanding Officer		ATTN: Library	1
Office of Naval Research			
Branch Office		Commander	
536 South Clark Street	1	David W. Taylor, Naval Ship	
Chicago, IL 60605	1	Research and Development Center	
·		Bethesda, MD 20084	1
Office of Naval Research		Demesua, MD 20001	
San Francisco Area Office		Naval Oceans Systems Center	
One Hallidie Plaza		San Diego, CA 92132	
Suite 601	_	Advini. Libert	1
San Francisco, CA 94102	1	ATTN: Library	_
an in literature		Naval Underwater Systems Center	
Naval Research Laboratory		Newport, RI 02840	
Washington, DC 20375	1	ATTN: Library	1
ATTN: Codes 6000	i	MI III. Zivimy	
6100	i	Naval Postgraduate School	
<b>6300</b>	1	Monterey, CA 93940	
2627	7	ATTN: Mechanical Engineering	
		Department	1
Naval Air Development Center		Debarement	
Code 606		Naval Weapons Center	
Warminster, PA 18974		China Lake, CA 93555	
ATTN: Mr. F.S. Williams	1	China Lake, CA 30000	1
**-		ATTN: Library	_
Naval Air Propulsion Test Center		Manual Air Contama Command	
Trenton, NJ 08628	_	Naval Air Systems Command	
ATTN: Library	1	Washington, DC 20360	1
		ATTN: Codes 52031 52032	ī
		J2002	

Organization	Copies	Organization	Copies
Naval Sea Systems Command Washington, DC 20362 ATTN: Code 05R	1	National Bureau of Standards Washington, DC 20234 ATTN: Metals Science and Standards Division	•
Naval Facilities Engineering		Ceramics Glass and Solid	1
Command Alexandria, VA 22331		State Science Division Fracture and Deformation	1
ATTN: Code 03	1	Division	1
Scientific Advisor Commandant of the Marine Corps Washington, DC 20380 ATTN: Code AX	1	Director Applied Physics Laboratory University of Washington 1013 Northeast Fortieth Street Seattle, WA 98105	1
Army Research Office		Defense Metals and Ceramics	
P.O. Box 12211 Triangle Park, NC 27709		Information Center Battelle Memorial Institute	
ATTN: Metallurgy & Ceramics	1	505 King Avenue Columbus, OH 43201	1
Program	1		1
Army Materials and Mechanics Research Center		Metals and Ceramics Division Oak Ridge National Laboratory	
Watertown, MA 02172 ATTN: Research Programs Office	1	P.O. Box X Oak Ridge, TN 37380	1
•	•		•
Air Force Office of Scientific Research/NE		Los Alamos Scientific Laboratory P.O. Box 1663	
Building 410 Bolling Air Force Base		Los Alamos, NM 87544 ATTN: Report Librarian	1
Washington, DC 20332	•	_	-
ATTN: Chemical Science Directorate Electronics & Materials	1	Argonne National Laboratory Metallurgy Division	
Sciences Directorate	1	P.O. Box 229 Lemont, IL 60439	1
Air Force Materials Laboratory			-
Wright-Patterson AFB Dayton, OH 45433	1	Brookhaven National Laboratory Technical Information Division	
Library		Upton, Long Island New York 11973	
Building 50, Room 134		ATTN: Research Library	1
Lawrence Radiation Laboratory Berkeley, CA	1	Office of Naval Research	
NASA Headquarters		Branch Office 1030 East Green Street	
Washington, DC 20546	•	Pasadena, CA 91106	1
ATTN: Code RRM	1		
NASA Lewis Research Center 21000 Brookpark Road Cleveland, OH 44135			
ATTN: Library	1		

### Distribution List B (Supplementary) (Fracture Mechanics and Erosion Processes)

Dr. W.F. Adler Effects Technology, Inc. 5383 Hollister Avenue Santa Barbara, CA 92105

Dr. G. Denman, Code LPJ AFML, Wright-Patterson AFB Dayton, OH 45433

Professor R. Bradt, Ceramics Section Materials Science Department Pennsylvania State University University Park, PA 16802

Dr. S.A. Bortz IITRI 10 W. 5th Street Chicago, IL 60616

Mr. E. Fisher Ford Motor Company Dearborn, MI 48121

Dr. W.G.D. Frederick AFML, Wright-Patterson AFB Dayton, Ohio 45433

Dr. P. Gielisse University of Rhode Island Kingston, RI 02881

Dr. M.E. Gulden International Harvester Solar Division 2200 Pacific Highway San Diego, CA 92138

Dr. D.P.H. Hasselman Virigina Polytechnic Institute Department of Materials Engineering Blacksburg, VA 24061

Dr. L.L. Hench Department of Metallurgy University of Florida Gainesville, FL 32611

Dr. A.H. Heuer Case Western Reserve University University Circle Cleveland, OH 44106 Mr. G. Hayes Naval Weapons Center China Lake, CA 93555

Dr. P. Jorgensen Stanford Research Institute Poulter Laboratory Meno Park, CA 94025

Dr. R.N. Katz Army Materials and Mechanics Research Center Watertown, MA 02171

Dr. H. Kirchner Ceramic Finishing Company P.O. Box 498 State College, PA 16801

Dr. B. Keopke Honeywell Inc. Systems and Research Center 2600 Ridgway Parkway P.O. Box 312 Minneapolis, MN 55440

Mr. Frank Koubek Naval Surface Weapons Center White Oak Laboratory Silver Spring, MD 20910

Dr. R. Jaffee Electric Power Resources Institute Palo Alto, CA

Dr. J. Ritter University of Massachusetts Department of Mechanical Engineering Amherst, MA 01002

Dr. P. Land AFML, Wright-Patterson AFB Dayton, Ohio 45433

Dr. F.F. Lange Rockwell International P.O. Box 1085 1049 Camino Dos Rios Thousand Oaks, CA 91360

Dr. J. Lankford Southwest Research Institute 8500 Culebra Road San Antonio, TX 78284 Dr. N. Macmillan Materials Research Laboratory Pennsylvania State University University Park, PA 16802

Mr. F. Markarian Naval Weapons Center China Lake, CA 93555

Dr. K.D. McHenry Honeywell Inc. Ceramics Center 1885 Douglas Drive Golden Valley, MN 55422

Dr. N. Perrone, Code 474 Office of Naval Research 800 N. Quincy Street Arlington, VA 22217

Dr. R.A. Queeney 126 Hammon Building Pennsylvania State University University Park, PA 16802

Mr. R. Rice Naval Research Laboratory Code 6360 Washington, DC 20375

Dr. D. Richardson AiResearch Manufacturing Company 4023 36th Street P.O. Box 5217 Phoenix, AZ 85010

Dr. Rustum Roy Materials Research Laboratory Pennsylvania State University University Park, PA 16802

Dr. R. Ruh AFML, Wright-Patterson AFB Dayton, OH 45433

Norton Company Industrial Ceramics Division Worcester, MA 01606 ATTN: Library

Dr. J.H. Rosolowski G.E. Company, R&D Center P.O. Box 8 Schenectady, NY 02301

State University of New York College of Ceramics Alfred University Alfred, NY 14802 ATTN: Library State University of New York Alfred University Materials Science Division Alfred, NY 14802

Dr. N. Tallan AFML, Wright-Patterson AFB Dayton, OH 45433

Mr. K. Letson Redstone Arsenal Huntsville, AL 35809

Charles Lewis EB1 Company, Inc. 91 Tolland Street East Hartford, CT 06108

Dr. D.A. Shockey Standford Research Institute Poulter Laboratory Menlo Park, CA 94025

Dr. G. Sines University of California at Los Angeles Los Angeles, CA 90024

Mr. J.D. Walton Engineering Experiment Station Georgia Institute of Technology Atlanta, GA 30332

Mr. L.B. Weckesser Applied Physics Laboratory Johns Hopkins Road Laurel, MD 20810

Dr. S.M. Wiederhorn Inorganic Materials Division National Bureau of Standards Washington, DC 20234

Dr. Paul D. Wilcox Sandia Laboratories Division 2521 Albuquerque, NM 87115

Dr. R.E. Tressler Ceramic Science Section 226 Steidle Building Pennsylvania State University University Park, PA 16802

Dr. T. Vasilos AVCO R & Advanced Development Division 201 Lowell Street Wilmington, MA 01887 Dr. Eugene A. Larson, President Blue River Laboratories P.O. Box 442 Lewistown, PA 17044

Mr. G. Schmitt AFML, Wright-Patterson AFB Dayton, Ohio 45433

Dr. M. Rosenblatt California Research and Technology 6269 Variel Avenue, Suite 200 Woodland Hills, CA 91364

Dr. A.G. Evans University of California Berkeley, CA 94720 Mr. D. Cassidy Ford Motor Company P.O. Box 1603 Dearborn, MI 48121

Dr. J. Brennan United Technologies Corporation United Technologies Research Center East Hartford, CT 06108

Professor M. Tomozawa Rensselaer Polytechnic Institute Department of Materials Engineering Troy, NY 12181

Murli H. Manghnani Hawaii Institute of Geophysics University of Hawaii Honolulu, Hawaii 96822 U.S.A.